PREPARED BY: MFMG

SUPERCEDING DATE: 11 SEP 86

SHEET:

APPROVED E

D110 10 10	
RMS/D&C	- 118

DATE:

PROJECT: SRMS ASS'Y MONEHCLATURE: DEC PANEL

SYSTEM: <u>PEC SUBSYSTEM</u> ASS'Y P/N: <u>\$1140E391</u>

SHEET: ____2

REF.	REV.	DRAWING REF. DESIGNATION	FATLURE MODE AND CAUSE	FATEURE EFFECT ON END JIEN	HOUR / FUNC. 2/188 CRITICALITY	RATIONALE FOR ACCEPTANCE
380	0	END EFFECTOR ANTO/OFF/ HAMMAL MODE SMITCH QTY-1 P/N ME 452-0102- 7306 ED 92020 SHEET 3	MODE: PERMANENT 10V MANUAL SELECT FLAG. CAUSE(S) (1) S/C 10V CONTACT	ALL MODES AND COMMANDS REMAIN AVAILABLE. IF EE AUTO/MANUAL SUITCH IS OFF, CAPTURE, OR RIGIDIZE COMMAND WILL LIMP THE ARM FOR THE DURATION OF THE COMMAND. UNRST CASE LOSS OF MISSION. SUBSEQUENT FABLURE CAN CAUSE UMENPECTED MOTION. UNEMPECTED LIMPING. UNAMMUNICIATED. CREW ACTION REQUIRED. REDUNDANT PATHS REMAINING CAPTURE OR RIGIDIZE TOV CONTACT	O VIBRATION: O THERMAL: THE DEC PANEL SYSTEM TESTS (TEST) WHICH VE QUALIFICATION THE SWITCH ETE PANEL ASSEMBLY QUALIFICATION O VIBRATION: O SHOCK: O THERMAL: O HUMIDITY: O EMC:	ITEM IS SUBJECTED TO THE FOLLOWING ACCEPTANCE TESTS AS PART OF THE DBC PAHEL ASSEMBLY. LEVEL AND DURATION - REFERENCE TABLE 1 +110 DEGREES F TO PLUS 10 DEGREES F (2 CYCLES - 9.5 HRS/CYCLE.) ASSEMBLY IS FURTHER TESTED AS PART OF THE RMS (1P518 RMS STRONGBACK TEST AND TP552 FLAT FLOOR RIFIES THE ABSENCE OF THE FAILURE MODE. TESTS WHAS BEEN QUALIFIED FOR ORBITER USE. THE DBC (HAS BEEN SUBJECTED TO THE FOLLOWING TEST ENVIRONMENTS. LEVEL AND DURATION - REFERENCE TABLE 1 20G/11 HS - 3 AXES (6 DIRECTIONS) 130 DEGREES F TO -23 DEGREES F (12 HRS PER CYCLE) (6 CYCLES) 95X (120 DEGREES F TO 82 DEGREES F CYCLE IN 16 HRS) 10 CYCLES TOTAL. MIL-STO-461 AS MODIFIED BY SL-E-0002 (TEST CEO! CEO2 CEO3, CSO1 (DC/AC), CEO3, CSO1 (DC/AC), CSO2, CSO6, REO2 (B/N), RSO2, RSO3, RSO4)

PREPARED BY: MFWG

SUPERCEDING DATE: 11 SEP 86

APPROVED BY: _

E:

JECT: SRMS SYSTEM: SYSTEM: ASS'Y A

SYSTEM: DAC SUBSYSTEM
ASS'Y P/N: 51140E391

SHEET:

REF.	REV.	DRAWING REF. DESIGNATION	FATCURE HODE AND CAUSE	FATLURE EFFECT ON END LIEN	HOUR / FUNC. 2/IRB RATIONALE FOR ACCEPTANCE CRITICALITY
380		END EFFECTOR AUTO/OFF/ MAMIATIN MODE SWITCH OTY-1 P/W ME 452-0102- 7306 ED 92020 SHEET 3	NODE: PERNAMENT 10V MANUAL SELECT FLAG. CAUSE(S): (1) S/C 10V CONTACT	ALL MODES AND COMMANDS REMAIN AVAILABLE. IF EE AUTO/MANUAL SUITCH 1S OFF, CAPTURE, OR RIGIDIZE COMMAND WILL 11MP THE ARM FOR THE DURATION OF THE COMMAND. WORST CASE LOSS OF MISSION. SUBSEQUENT FAILURE CAN CAUSE UMEXPECTED NOTION. UNEXPECTED LIMPING. UNAXIMUMCIATED. CREW ACTION REQUIRED. REDUNDANT PATHS REMAINING CAPTURE OR RIGIDIZE TOV CONTACT	MERMETICALLY SEALED TOGGLE SWITCHES ARE PROCURED TO ROCKWELL SPECIFICATION MC552-0102. ROCKWELL PART NO. MC452-0102 QUALIFICATION AND ACCEPTANCE TESTING OF SWITCHES IS PERFORMED TO R.I. SPEC. MC552-0102. RECETVING INSPECTION VERIFIES THAT SWITCHES RECEIVED ARE AS JOENTIFIED IN THE PROCURENEST DOCUMENTS, THAY MO PHYSICAL DANAGE MAS OCCURRED TO SUITCHES DURING SHIPMENT, THAY MO PHYSICAL DANAGE MAS OCCURRED TO SUITCHES DURING SHIPMENT THAT THE RECEIVING DOCUMENTS PROVIDE ADEQUATE TRACEABILITY INFORMATION AND ACCEPTANCE TEST DATA IDENTIFIES ACCEPTABLE PARTS. PARTS ARE INSPECTED THROUGHOUT MANUFACTURE AND ASSEMBLY AS APPROPRIATE TO THE MANUFACTURING STAGE COMPLETED. THESE INSPECTIONS INCLIDE, COMPONENT MOUNTING TO FRONT PANEL INSPECTION, SOLDERING OF WIRES TO SWITCH CONTACTS, WIRE ROUTING STRESS RELIEF OF WIRES ETC., OPERATORS AND INSPECTIONS ARE TRAINED AND CERTIFIED TO MASA MHB 5300.4(3A) STAMBARD, AS MODIFIED BY JSCORBOOOA. PRE-TEST INSPECTION OF DAC PANEL ASSY INCLUDES AN AUDIT OF COMER TIER INSPECTION COMPLETION, AS BUILD CONFIGURATION VERIFICATION TO AS DESIGN ETC. (SPAR/GOVERNMENT REP. MANUFACTURE WERFFICATION OF TEST PERSONNEL, TEST DOCUMENTS, TEST FOULD PHENT CALIBRATION TEST PERSONNEL, TEST DOCUMENTS, THEY ROUTE HER AS APPLICABLE, AND THE GOVERNENT REPRESENTATIVE, PRIOR TO THE STANT OF ANY FORMAL TESTING (ACCEPTANCE OR GULLFFICATION). ACCEPTANCE TESTING (ATP.) INCLUDES AMBIENT PERFORMANCE, THERMAL AND VIBRATION TESTING, (SPAR/GOVERNMENT REP. MANUFACTORY DESCRIPTION OF BENT OR PUSHBACK CONTACTS ETC. SUB-SYSTEM PERFORMANCE TESTING (ATP.) INCLUDES AN AMBIENT PERFORMANCE TEST. (MANDATORY INSPECTION POINT). SRMS SYSTEMS PERFORMED AT EACH STAGE OF INTEGRATION, WHICH INCLUDES GROUNDING CHECKS, INTER CONNECT CABLE VERIFICATION, CONNECTOR INSPECTION FOR BENT OR PUSHBACK CONTACTS ETC. SUB-SYSTEM PERFORMANCE TESTING (ATP.), INCLUDES AN AMBIENT PERFORMANCE TEST. (MANDATORY INSPECTION POINT). SRMS SYSTEMS TESTING STRONGGROCK AND FLAT FLOOR ANBIENT PERFORMANCE TEST. (PANDATORY INSPECTION POINT).

PREPARED BY: MFWG

SUPERCEDING DATE: 11 SEP 86

APPROVED BY: _

IE: _____

CRITICAL ITEMS LIST

PROJECT: SRMS

ASS'Y HOMENCLATURE: DEC PANEL

ASS'Y P/N: \$150E391

SHEET: 4

PMEA REF.	REV.	DRAWING REF. DESIGNATION	FATLURE PROBE AHO CAUSE	FAILUME EFFECT ON END ITEM	HOUR / FUNC. 2/18 RATIONALE FOR ACCEPTANCE CRITICALITY
380		ENO EFFECTOR AUTO/OFF/ MANUAL MODE SVITCH GTY-1 P/N ME 452-0102- 7306 ED 92020 SHEET 3	MODE: PERMANENT 10V MANUAL SELECT FLAG. CAUSE(8): (1) S/C 10V CONTACT	ALL MODES AND COMMANDS REMAIN AVAILABLE. IF EE AUTO/MANUAL SWITCH IS OFF, CAPTUME, OR RIGIDIZE COMMAND WILL LIMP THE ARN FOR THE DURATION OF THE COMMAND. WORST CASE LOSS OF MISSION. SUBSEQUENT FAILURE CAN CAUSE UMEMPECTED MOTION. LIMEMPECTED LIME	THERE HAVE BEEN NO FAILURES ASSOCIATED WITH THIS FAILURE MODE ON THE SAMS PROGRAM.
		ļ			

REPARED BY: MFWG		SUPERCEDING DATE: 11 SEP 86	APPROVED BY:	t:
------------------	--	-----------------------------	--------------	----

CRITICAL ITEMS LIST

PROJECT: SRMS ASS'Y NOMENCLATURE: DEC PANEL SYSTEM: DAC SUBSYSTEM ASS'Y P/N: \$1140E391

eel: S

380 0 END EFFECTOR NUMBERS AND COMMINDS REMAIN AVAILABLE. IF SAVITON OF FLORE SELECT FLAG. SUFFOR 12 OFF, CAUSE(S): CAPILIE, OR OPERATIONAL EFFECTS OPERATI	PREA REF.	DRAWING REF. DESIGNATION	FATLURE MUDE AND CAUSE	FATEURE EFFECT ON END TIEM	NOUN / FUNC. 2/TRB RATIONALE FOR ACCEPIANCE CRETICALITY
COMMAND ED 92020 SMEET 3 COMMAND SMEET 3 MOME	380	AUTO/OFF/ MARIAL MODE SWITCH OTY-1 P/M ME 452-0102- 7306 ED 92020	PERMANENT 10V MANUAL SELECT FLAG. CAUSE(8): (1) 8/G 10V	COMMANDS REMAIN AVALLABLE. IF EE AUTO/MANUAL SUFFCN 13 OFF, CAPTURE, OR RIGID12E COMMAND WILL LIMP THE ARN FOR THE COMMAND. WORST CASE LOSS OF MISSIOM. SUBSEQUENT FAILURE CAN CAUSE LIMERPECTED MOTION REQUIRED. REDUNDANT PATHS REPAILINED. REDUNDANT PATHS REPAILINED CAPTURE OR RIGID1ZE TOY	NOME. SUBSEQUENT FAILURE RESILTS IN PERMANENT LIMPING LIMEN IN ANY COMPUTER SUPPORTED MODE. CREW ACTION NOME CREW TRAINING HOME MISSION CONSTRAINTS HOME SCREEN FAILURES B: NO ORBITER AUMENICIATION ON DISPLAY. DETECTABLE BY GMD. CMRSD OFFLINE EXERCISE DEC PANEL SE AUTO/MANUAL MODE SWITCH. VERIFY SE MODE BIT IN MICHU/DEC PANEL DATA BUS. CMRSD ONLINE INSTALLATION NOME OMRSD ONLINE TURNAROUND MISH SE AUTO/MANUAL/OFF MODE SWITCH IN *DFF* POSITION

PARED BY: MING _____ SUPERCEDING DATE: 11 SEP 86

APPROVED BY: